

**WARRANTY:** 

None

# **Product Support Bulletin 2010-002**


245 W. Forest Hill Avenue Oak Creek, WI 53154


Contact: Gary D. Van Deluyster, Service Manager - Phone: 800-445-9258 - Fax: 414-766-2260


## Maintenance of Way ~ Work Equipment Bulletin

DATE:	June 9, 2010		
SUBJECT:	Reinforced Spotting Cylinder Mounting – 34700033-570		
RATING:	DIRECTIVE (Action is required)	X ALERT (Potential Problem)	
	INFORMATION (Action is optional)	PRODUCT IMPROVEMENT (Enhance Product)	
MACHINE MODEL(S):	SP2R – Spike Puller		
SERIAL NUMBER(S):	310001-310132		
SUMMARY:	The mounting that supports the Workhead Spotting Cylinder could break off if the Spike Claws were to hit an obstruction while working. See Figure 1 on Page 2.		
OPERATIONAL IMPACT:	If the mounting breaks, the Workhead is free to move and could hit the cab and break the front window.		
ACTION:	The Spotting Cylinder Mounting must be reinforced with larger welds. Follow the instructions beginning on Page 3. <b>Make sure to follow all Lock Out-Tag Out Drocedures.</b> If the mounting itself is damaged or missing, a new mounting may be ordered through the Nordco Parts Department. Please call 1-800-647-1724 and order p/n 34700033-570. Machines with serial numbers above 310132 have been built with the reinforced mounting and will not have to be modified.		
		cylinder Mounting, it is recommended that ussed in PSB 2009-006 which is included	

Page 1 of 8
Please Turn the Page







**Figure 1**Spotting Cylinder Mounting


### **Spotting Cylinder Mounting Reinforcing Instructions**


# REWORK SPOTTING CYLINDER MOUNTING ON SP2R FRAME


Note: Be sure to use all appropriate personal protective equipment, including full face shield for grinding, gloves, and eye protection for welding.

disc won't fit; use a cutoff wheel. Grind the weld flush with the frame rail, but do not over-grind. Clean and prep frame cylinder mounting bracket will separate from the frame. If you have to grind down the weld in a tight area, a grinding Grind out the majority of the weld so that when you strike it with a hammer, it will crack the leftover weld and the surface for welding.


The cylinder mounting bracket will be reused. Rework this bracket by adding a bevel at a 30deg angle. Then weld pracket to the frame as shown in the following pages.







### **NORDCO Product Support Bulletin 2010-002**





### **Product Support Bulletin 2009-006**

245 W. Forest Hill Avenue Oak Creek, WI 53154

Contact: Gary D. Van Deluyster, Service Manager - Phone: 800-445-9258 - Fax: 414-766-2260

### Maintenance of Way ~ Work Equipment Bulletin

DATE:	June 30, 2009		
SUBJECT:	Workhead Slider Stop Bolt Kit – 98310008		
RATING:	DIRECTIVE (Action is required)	X ALERT (Potential Problem)	
	INFORMATION (Action is optional)	PRODUCT IMPROVEMENT (Enhance Product)	
MACHINE MODEL(S):	SP2R Dual Rail Spike Puller		
SERIAL NUMBER(S):	310001-310139 except 310131, 310132, 310137, 310138		
SUMMARY:	There have been reports of the lower front cab windows being broken by the Pulling Head if the Pulling Head Spotting Cylinder or its attachment bracket breaks. Installing this kit will limit the Pulling Head travel and prevent contact with the cab windows.		
OPERATIONAL			
IMPACT:	A broken lower front cab window can obstruct the operator's vision of the work area resulting in slower production.		
ACTION:	The 98310008 Workhead Slider Stop Bolt Kit contains 2 each of ½" x 3-1/4 Capscrew, p/n 2775356 and ½" Locknut (Stover Nut), p/n 3042025. Each kit will modify one complete machine. Installation involves drilling a 9/16" diameter hole through the cab end of the Upper Guide Channel on each side of the machine and installing the Capscrew and Locknut. See Figure 1 on Page 2 for drilling location Installation should take less than 1 hour. Be sure to follow all Lock Out/Tag Outprocedures before installing this kit.		
	Machines s/n 310131, 310132, 310137, 310138 and 310140 and higher have stops included as part of the machine frame and do not require this kit.		
WARRANTY:	None		

Page 1 of 2 Please Turn the Page



### NORDCO Product Support Bulletin 2009-006




Figure 1
98310008 Workhead Slider Stop Kit Installation Instructions