



PRODUCT SUPPORT BULLETIN BULLETIN NO. 351

DATE: **July 31, 2002**

MACHINE: **LS Auto-Lift**

SERIAL
NUMBER(S): **790620 – 790628, 790634, 790636 - 790640**

SUBJECT: **Oil Cooler Mounting Upgrade Kit - 98790134**

There have been reports of the factory-installed oil cooler failing due to tearing out of the mounting holes in the cooler. A flexible mounting bracket and the thin material of the cooler Mounting flange cause this problem.

An **Oil Cooler Mounting Upgrade Kit, p/n 98790134** is available for the machines shown above. This kit includes a redesigned Oil Cooler Support and four **Spacers, p/n 82636150**. These spacers fit between the two mounting flanges of the cooler to double the thickness of material supporting the cooler. Hardware and installation instructions are also included.

This kit can be installed in about 2-3 hours and requires some minor cutting and welding to complete the installation.

Machines with serial numbers 790629 – 790633 and 790635 have been retrofitted with this kit in the field. Machines s/n 790641 and higher will have this upgrade installed at the factory.

