



Product Support Bulletin 2011-002

245 W. Forest Hill Avenue
Oak Creek, WI 53154

Contact: Travis Dittberner, Service Manager – Phone: 800-445-9258 – Fax: 414-766-2260

Maintenance of Way ~ Work Equipment Bulletin

DATE: December 12th, 2011

SUBJECT: Internal LVDT Rail Lift Cylinder Kit 98760071

RATING: **DIRECTIVE**
(Action is required)

ALERT
(Potential Problem)

INFORMATION
(Action is optional)

PRODUCT IMPROVEMENT
(Enhance Product)

MACHINE MODEL(S): Tripp Model A
Tripp Model B
Tripp Model C
Tripp Model D

SERIAL NUMBER(S): Tripp S/N 760125 through S/N 760402

SUMMARY: A new rail lift cylinder with an INTERNAL LVDT has been developed that eliminates the need for the external LVDT mounted to the Rail Lift Assembly.

Cylinders must be replaced in pairs when ordering for the first time. A kit, Nordco P/N 98760071 is available for purchase and includes two cylinders, cables, and instructions for removing the old cylinders and LVDTs.

This cylinder is standard on machine S/N's 760403 and above.

OPERATIONAL IMPACT: None. Eliminates possible damage to the external LVDT's.

ACTION: Customer install would be required. Allow approximately 3-4 hours for installation both sides of the machine.

WARRANTY: None