

## **Product Support Bulletin 2022-005**

245 W. Forest Hill Avenue Oak Creek, WI 53154


Contact: Technical Support, Phone: 800-445-9258 or Email: NordcoTechService@wabtec.com

## Maintenance of Way ~ Work Equipment Bulletin

DATE:	November 07, 2022	
SUBJECT:	HSTX Required Propel Manifold Assembly Replacement	
RATING:	X DIRECTIVE (Action is required)	ALERT (Potential Problem)
	INFORMATION (Action is optional)	PRODUCT IMPROVEMENT (Enhance Product)
MACHINE MODEL(S):	HSTX Tampers	
SERIAL NUMBER(S):	S/N's starting at 220101 - 220105, 220109 & 220110, 220113 - 220119, 220123, and 220200 & 220201.	
SUMMARY:	The original Propel manifold assembly (P/N 50072206), that was installed when the Tamper was originally delivered requires replacement with the 'GEN 2' version (P/N 50072210) that is used on later Model HSTX machines (S/N 220202 & above). Nordco will no longer be able to support the original manifold assembly, due to limited parts availability and less than optimal cartridge valve durability and performance.	
OPERATIONAL IMPACT:	The new 'GEN 2' manifold assembly (P/N 50072210) is only marginally different in appearance. The propel functionality will remain essentially the same. The only exception is the removal of the adjustable Decel Valve found inside the cab. This feature is no longer required with the 'GEN 2' manifold.	
ACTION:	This new 'GEN 2' manifold is a bolt-in replacement for the original manifold.  The new manifold will come in a kit with all the required hardware, new	

Page 1 of 2 Please Turn the Page

hoses, and fittings needed to complete the installation.



## **NORDCO Product Support Bulletin 2022-005**

## **WARRANTY:**

The complete kit (P/N 98220070) will be sent out under warranty to owners of each machine listed above. Please contact the Nordco Service Dept. at 1-800-445-9258 with the S/N(s) of your machine(s). When you contact us, we will coordinate an onsite visit with one of our technicians to assist in the installation of the kit and perform final adjustments and testing. This will be required to complete this issued Nordco PSB Directive.