



PRODUCT SUPPORT BULLETIN BULLETIN NO. 285

DATE: **March 8, 1999**

MACHINE: **M3-B, M3-C**

SERIAL

NUMBER(S): **M3-B: 450012-22, 450049-50, 450057-58**

M3-C: 450060-61, 450063

SUBJECT: **Revised Cobra brake shoe lever, P/N 47381300**

The brake lever on these M3 machines would interfere with the brake spring retaining plate preventing complete wear of the brake shoe.

The Cobra brake shoe lever, part number 47381300, has been revised to allow a full 1" of brake shoe wear. Only M3-B and M3-C machines in the above serial number range should have the levers changed out to allow full use of the brake shoe. The lever on the spring end of the brake cylinder is the only lever that needs to be changed. The drawing below shows the configuration of the revised lever.

