

**WARRANTY:** 

## **Product Support Bulletin 2005-007**

245 W. Forest Hill Avenue Oak Creek, WI 53154

Contact: Gary D. Van Deluyster, Service Manager – Phone: 800-445-9258 – Fax: 414-766-2379

## Maintenance of Way ~ Work Equipment Bulletin

DATE:	October 31, 2005				
SUBJECT:	New CX Hammer Operation and Parts Manuals				
RATING:		CTIVE n is required)	ALER (Poter	<b>T</b> ntial Problem)	
		RMATION n is optional)		nce Product)	
MACHINE MODEL(S):		CX Hammer Spiking Machines			
SERIAL NUMBER(S):		410500 and above			
SUMMARY:		Due to design improvements to several different engine op manuals for the CX Hammer manual for your particular of 49454100 part numbers for machine will no longer be available.	tions, there . Use the lis nachine. Th the Operation	are now several different t below to order the correc- ne original 49455283E and	nt et d
OPERATIONAL IMPACT:		There are different mechanical parts sheets and electrical schematics required for the various types of engines. A manual specific to a particular machine will ensure that the parts sheets and schematics are correct for a given machine/engine combination.			
ACTION:		Replacement Operation and I manual numbers shown below manual number for your partic	v. Please ma	ake sure to order the correc	
		Machine S/N 410500 to 410603S/N 410604 and Above with John S/N 410604 and Above with Cum S/N 410604 and Above with John	Deere 4045D mins B4.5T En	gine <b>49454103</b>	

None