

WARRANTY:

Product Support Bulletin 2005-009

245 W. Forest Hill Avenue Oak Creek, WI 53154

Contact: Gary D. Van Deluyster, Service Manager – Phone: 800-445-9258 – Fax: 414-766-2379

Maintenance of Way ~ Work Equipment Bulletin

DATE:	November	10, 2005		
SUBJECT:	3" bore Machine Lift Cylinder - 28552671			
RATING:	DIRECTIVE (Action is required)		ALERT (Potential Problem)	
		RMATION n is optional)	x PRODUCT IMPROVEMENT (Enhance Product)	
MACHINE MOI	DEL(S):	Auto-Lift Model A Auto-Lift Model B Auto-Lift LS		
SERIAL NUMBER(S):		200-232, 500-790659, 791001-791008		
SUMMARY:			nine Lift Cylinders, p/n 28552434, are bein hine Lift Cylinder, p/n 28552671. See	
OPERATIONAL IMPACT:		There have been several modifications to these machines over the years that have increase the weight of this machine to the point where there is not enough lifting force in some circumstances, such as near highway crossings. To solve this problem, the cylinder bore has been increased to 3". This will generate an additional lifting force of 5,184 pounds per cylinder at 2,400 psi.		
ACTION:		cylinders on the machine. T frame of the machine. The li older machines) will bolt to well. However, the packing l	a direct replacement for the 2-1/2" bor There are no modifications required to th limit switch bracket (or opto-switch box of the new cylinder without modification at kit for the 3" cylinder is different from the packing kit for the 3" bore cylinder is	
		The original 28552434 cylinder for them will be filled with the	ders are no longer available and all order 3" bore 28552671 cylinder.	

Page 1 of 2 Please Turn the Page

None






Figure 1 (Machine Lift Cylinder 28552671)