



Product Support Bulletin 2009-005

245 W. Forest Hill Avenue
Oak Creek, WI 53154

Contact: Gary D. Van Deluyster, Service Manager – Phone: 800-445-9258 – Fax: 414-766-2260

Maintenance of Way ~ Work Equipment Bulletin

DATE: June 30, 2009

SUBJECT: Dust Hood Bumper Pad Material Change – 52890001

RATING: **DIRECTIVE**
(Action is required)

ALERT
(Potential Problem)

INFORMATION
(Action is optional)

PRODUCT IMPROVEMENT
(Enhance Product)

**MACHINE
MODEL(S):** CX Hammer


**SERIAL
NUMBER(S):** All with Bulk Loader and Dust Collection System

SUMMARY: The 52890001 Dust Hood Bumper Pad is mounted to the end of the Dust Hood in the Operator's Cab to protect the operator from coming into contact with the steel edge of the Dust Hood. See Figure 1 on Page 2. It was originally made of gum rubber. The material has been changed to reinforced neoprene which will increase the service life of the pad.

**OPERATIONAL
IMPACT:** If the Bumper Pad is damaged, the steel end of dust collector is exposed. Possible injury to the operator could result from contact with the steel edge of the Dust Hood.

ACTION: All Dust Hood Bumper Pads should be inspected and if the pad is damaged, it should be replaced with a new pad. To order new pads, contact the Nordco Parts Department at 1-800-647-1724. All new pads are made from reinforced neoprene.

WARRANTY: None






Figure 1
Bulk Loader Dust Hood and Bumper Pad