

Mark III - Production and Switch Tampers

Exchange Components



Vibrator Exchanges



JV68336-02EX: Electromatic Vibrator



JE-2010512-0-02EX: Hydraulic Vibrator with Motor and Coupler

JE-2010512-0-0200EX: Hydraulic Vibrator without Motor and Coupler

Clamp Assemblies




J0-2201685-2-01: Rebuilt Roller Clamp Assembly Complete




JW683484LEX: Exchange Rail Clamp Assembly (Left)

JW683484REX: Exchange Rail Clamp Assembly (Right)

Workhead and Frame Assembly Exchanges



JE-2011165-0-15: Rebuilt Workhead Frame Assembly (Left) - Does not include rear sliders or support arms



JE-2011165-0-16: Rebuilt Workhead Frame Assembly (Right) - Does not include rear sliders or support arms




JE-2011165-0-15C-R: Rebuilt Workhead Frame Complete Assembly (Left) - Ready to install




JE-2011165-0-16C-R: Rebuilt Workhead Frame Complete Assembly (Right) - Ready to install


Workhead and Frame Assembly Exchanges (Cont.)



JA5665WAA: Workhead Frame Complete Assembly with Vibrators (Left)



JA5665WAB: Workhead Frame Complete Assembly with Vibrators (Right)



JE-210706-0-01REX: Rebuilt Vibrator Carrier (Right)



JE-210706-0-01LEX: Rebuilt Vibrator Carrier (Left)

Combo Clamp Assembly



JA7608VAA-R: Combo Clamp Assembly with BTI Solid Tungsten Carbide Wear Surfaces



JB5708XAA: Hook Extend Cylinder

Countershaft Assembly



JX754110AEX: Exchange Rebuilt Countershaft Assembly (No Pulley)

JX754110ACEX: Exchange Rebuilt Countershaft Assembly (With Pulley)

Stator



JE-1404809-0-01EX: Rebuilt Stator - Rewound and Notched

Jack Shaft Assembly



J02201787-0-01EX: Rear Jack Shaft Assembly

www.nordco.com

107 N. US Highway 45
PO Box 162
Arcola, IL 61910 USA
Phone: 217-268-4823

