



Product Support Bulletin 2015-002

245 W. Forest Hill Avenue
Oak Creek, WI 53154

Contact: Luke Banasik – Asst. Manager, Service & Technical Support
Phone: 800-445-9258 or Email: TechSupport@Nordco.com

Maintenance of Way ~ Work Equipment Bulletin

DATE: April 7, 2015

SUBJECT: Cab door latch open release handle replacement.


RATING:	<input type="checkbox"/> DIRECTIVE (Action is required)	<input type="checkbox"/> ALERT (Potential Problem)
	<input checked="" type="checkbox"/> INFORMATION (Action is optional)	<input type="checkbox"/> PRODUCT IMPROVEMENT (Enhance Product)

MACHINE MODEL(S): SP2R based cab versions. This will include a variety of models starting with the AA2R, NVCAR, QD2R, RPI, SP2R and SCREW REMOVER.

SERIAL NUMBER(S):

- AA2R S/N 650001 thru 650054
- NVCAR S/N 140300 thru 140333
- RPI S/N 720125 thru 720156
- QD2R S/N 120400 thru 120410
- SP2R S/N 310001 thru 310312
- SCREW REMOVER S/N 130400 thru 130402

SUMMARY: A redesigned latch open release handle, P/N 42030163 has been developed by Nordco. This latch handle is the one that releases the door from inside the cab when the door is in the open position (latched against cab wall). The handle has been redesigned to rest in a more vertical position than in the horizontal position it is currently in. This handle is also available with kit P/N 98310034 which will take of both cab doors. The kit also includes a replacement 1/4" bolt, which limits excess travel of the handle.



NORDCO Product Support Bulletin 2015-002

OPERATIONAL

IMPACT:

The current horizontal position allows the handle to extend in the cab door way opening a couple of inches, leaving it in position to get damaged or stepped on. The replacement handle allows it to be clear of the opening to prevent any possible damage.

ACTION:

Verify your machine is the model and serial number range listed on page 1. If your machine is in those groups you should order Nordco Kit P/N 98310034. The replacement is very simple. It only requires removing a couple of cotter pins and a clevis pin to take off the old handle and then install new handle and cotter pins.

WARRANTY: None.



Old handle position.



New handle position.

<http://www.nordco.com/Customer-Support/Maintenance-of-Way-Equipment/Product-Support-Bulletins.htm>