



PRODUCT SUPPORT

BULLETIN NO. 254

DATE: June 1, 1997

MACHINE: **HYDRA HAMMER MODEL A**
HYDRA HAMMER MODEL B
M3 MODEL A - SPIKERS

PRODUCTION

DATES: All

SUBJECT: **GUIDE RODS**

Guide Rod (Nordco Part Number 68587201) currently used on Hydra Hammer Models A and B, and the M3 Model A Spikers is no longer available. When placing a repair part order, please order Guide Rod (Nordco Part Number 14368888). See Figure 1 below, for differences between the old guide rod and the new guide rod.

This guide rod works better with the Guide Rod Clamp Assembly introduced in Product Support Bulletin #213 and shown in the drawing below.

Please contact your NORDCO Representative or NORDCO Parts Sales for prices and availability.




Figure 2.