EQUIPMENT SERVICES BULLETIN



Current information on Nordco Maintenance-of-Way Machine Parts, Repair and Upgrade Kits, Exchange Components and Rebuilt Machines

ISSUE 66 June 2014











Seeing is Believing: More parts photos added to Nordco website

We keep adding part photos to the Nordco website, making it easy for you to identify the component you need. There are close to <u>3,000 photos</u>, many of which also include the weight of the item. Go to <u>www.nordco.com</u> and select <u>Parts/Manuals</u>. Then click on <u>Parts Catalog - Maintenance of Way</u>. Now you can search for parts by part number, keyword or machine type. When you see the camera icon click on it to reveal the photo.


Featured Rebuilt Component: Combo Clamp Assemblies

Part number: JA7608VAA MK III Combo Clamp Assembly

JA7608VAK MK IV Combo Clamp Assembly

What it does: Complete, ready to install Combo Clamp

Assemblies feature tungsten carbide wear surfaces. Available in Jupiter or non-Jupiter configuration. Consult Nordco for available options. Exchange or purchase outright.



Nordco offers a wide selection of kits and parts for the MK III, MK IV and Jackson 6700 tampers, ready for fast delivery. Contact Nordco for more information, or search the Parts section at www.nordco.com.

NEW FROM NORDCO

Featured Product: Circuit Breaker Replacement Kit

Part number: 98840023

Used with: Most Nordco maintenance-of-

way machines

What it does: Selection of frequently used circuit

breakers for multiple machines, available when you need them.

Description: The kit includes the following circuit breakers, all with manual reset:

PART# QTY. **DESCRIPTION** 5128946 1 5 AMP CIRCUIT BREAKER 5128935 5 10 AMP CIRCUIT BREAKER 3 5128936 15 AMP CIRCUIT BREAKER 5128937 3 20 AMP CIRCUIT BREAKER 5128938 1 25 AMP CIRCUIT BREAKER 5128939 30 AMP CIRCUIT BREAKER

REPAIR & MAINTAIN MACHINE

98840023 Circuit Breaker Replacement Kit.

Protect and maintain your machine air conditioner with these kits

The warm weather months are finally here, so you can't afford to have down time because of problems with a machine's air conditioning unit. Here are a couple of suggestions from Nordco to help prevent damage and keep your air conditioner in good working order.

98412440 A/C Dual Condenser Guards Kit: For use on any CX Hammer after S/N 410592 with Red Dot air conditioner with dual condenser unit. Guards shield condenser fans from loose spikes that may fall during loading, and from debris during operation.

98410496 Air Conditioner Maintenance Kit: For CX Hammer, TRIPP Tie Exchanger and other Nordco machines with roof-mounted Red Dot air conditioner. Commonly used components to maintain and repair air conditioner. Kit includes one each of 22239500 A/C Expansion Valve: 660100 Receiver Dryer Kit; 5126103 Binary Switch; 5126097 Cab Temp Control Dial; 25730008 A/C Compressor Kit; and 22239911 Condenser Puller Fan.

IPROVE MACHINE PRODUCTIVITY

REPAIR & MAINTAIN **MACHINE**





98412440 A/C Dual Condenser Guards Kit and 98410496 Air Conditioner Maintenance Kit.

Featured Machine: SP2R Spike Puller 2-Rail



This month we are highlighting popular exchange components and repair and upgrade kits for the SP2R Spike Puller, as well as some kits you may not be as familiar with. Contact Nordco Parts for a complete list of available parts and kits for your application, or use the easy-to-search parts catalog at www.nordco.com.

Various P/N Exchange Pulling Head Assembly. Complete workhead replacement package. Right and left hand assemblies. Options include standard spikes, Evergrip spikes and power lockups. Consult Nordco for the right component for your application.

MACHINE



98350136 Workhead Service Kit - Standard Spike: Includes selection of parts commonly used to service workhead on SP2R, as well as Grabber, Grabber LS-2 and Super Claw. For Evergrip Spikes order 98350135.

2-Speed Travel Kit: Two speed capability offers increased torque in work mode without compromising travel speed. Also offers improved ability to negotiate steeper grades and ramps when loading machine on trucks or flatcars.

98350049 Claw Assembly Kit: Replacement kit for SP2R. Includes four 46650037 Spike Puller Claw and 54259810 Claw Retainer Pin.

98310102 Dacromet Bolt Kit for Left Manifold 50078931: Valve mounting bolts with anti-corrosion coating resist seizing up in tapped holes

REPAIR & MAINTAIN

REPAIR & MAINTAIN MACHINE




IMPROVE MACHINE PRODUCTIVITY

WEAR PARTS



PREVENTATIVE MAINTENANCE

98310103 Dacromet Bolt Kit for Right Manifold 50078932.



Left: 98310102 Dacromet Bolt Kit for Left Manifold. Right, from top: Exchange Pulling Head Assembly; 98350136 Workhead Service Kit; manifold and components included in 98310020 2-Speed Travel Kit; and 98350049 Claw Assembly Kit.



Contact Nordco Aftermarket Parts Sales & Service

Ph: 1-800-647-1724 7:30 a.m. - 5 p.m. Central Time Monday - Friday Fax: 414-766-2379 Email: Parts Sales@nordco.com Request an order or guotation: www.nordco.com Nordco Inc. 245 W. Forest Hill Ave. Oak Creek, Wisconsin 53154 USA