

# TRIPP - Tie Exchanger


Exchange Components



## TRIPP Gripper Assembly

Part Number: **90760025**

- New gripper cylinder
- New BTI tie clamps
- New bushings
- New gripper pivot mounting
- New tie gripper arms
- Sandblasting, painting, and assembly ready to hang



## TRIPP Workhead

Part Number: **90760021**

- New shims, wear pads, bushings, and mounting hardware
- Repair or replacement of main housing and exchanger arms
- New sheathed hoses for complete assembly
- New or re-manufactured manifold
- New wiring and junction boxes
- New BTI grippers
- New or rebuilt cylinders
- New swivel adapters
- Sandblasting, painting, and assembly ready to hang



## One Side Boom and Gripper

Part Number: **90760026**

No photo available



Use your smartphone to scan this code for more information.

## Rail Clamp

Part Number: **90760132**

- New clamp frame
- New or rebuilt rail lift levers
- New sheathed hoses for complete assembly
- New rail clamp cylinder
- New rollers, pins, and bushings
- New wheel axles
- Sandblasting, painting, and assembly ready to hang



## Axle Assembly

Part Number: **90760095**

- New or rebuilt axle
- New bearings
- New axle nuts
- New bushings
- New pillow block bearings
- New spacers, insulation strips, and rings
- Sandblasting, painting, and assembly ready to hang



[www.nordco.com](http://www.nordco.com)

245 W. Forest Hill Avenue  
Oak Creek, WI 53154 USA  
Phone: 414-766-2180  
Fax: 414-766-2379

