

# Mark I - Production and Switch Tampers

Exchange Components



## Vibrator Exchanges



**JV68336-02EX:** Electromatic Vibrator



**JE-2010512-0-02EX:** Hydraulic Vibrator with Motor and Coupler

**JE-2010512-0-0200EX:** Hydraulic Vibrator without Motor and Coupler

---

## Clamp Assemblies



**J0-2201685-2-01:** Rebuilt Roller Clamp Assembly Complete



**JW683484LEX:** Exchange Rail Clamp Assembly (Left)

**JW683484REX:** Exchange Rail Clamp Assembly (Right)

## Countershaft Assembly



**JX754110AEX:** Exchange Rebuilt Countershaft Assembly (No Pulley)


**JX754110ACEX:** Exchange Rebuilt Countershaft Assembly (With Pulley)

---

## Workhead Assemblies



**JW68283-03-REX:** Rebuilt Vibrator Carrier (Right)



**JW68283-03-LEX:** Rebuilt Vibrator Carrier (Left)

[www.nordco.com](http://www.nordco.com)

107 N. US Highway 45  
PO Box 162  
Arcola, IL 61910 USA  
Phone: 217-268-4823

